

CBJ CORROSION CONTROL PROJECT  
H-PILE PHOTOS



Cap A6 from North



Cap A6 from Northwest

**FOR INFORMATION ONLY**

Conditions may have changed.  
Contractor responsible to verify  
current conditions



**CBJ CORROSION CONTROL PROJECT  
H-PILE PHOTOS**



Cap A6 from Southeast



Cap A6 from Southwest



Cap A7 from Southwest

**FOR INFORMATION ONLY**

Conditions may have changed.  
Contractor responsible to verify  
current conditions



**CBJ CORROSION CONTROL PROJECT  
H-PILE PHOTOS**



Cap A7 from Southwest

**FOR INFORMATION ONLY**

Conditions may have changed.  
Contractor responsible to verify  
current conditions

**CBJ CORROSION CONTROL PROJECT  
H-PILE PHOTOS**



Cap B7 from North



Cap B7 from East



Cap B7 from Northeast

**FOR INFORMATION ONLY**

Conditions may have changed.  
Contractor responsible to verify  
current conditions



**CBJ CORROSION CONTROL PROJECT  
H-PILE PHOTOS**



C10 from Northeast




Cap C10 from Northeast

**FOR INFORMATION ONLY**

Conditions may have changed.  
Contractor responsible to verify  
current conditions

**CBJ CORROSION CONTROL PROJECT  
H-PILE PHOTOS**



Cap C9.7 from West

**FOR INFORMATION ONLY**

Conditions may have changed.  
Contractor responsible to verify  
current conditions



**CBJ CORROSION CONTROL PROJECT  
H-PILE PHOTOS**



Cap C7 from Northwest



C7 Cap from Northeast

**FOR INFORMATION ONLY**

Conditions may have changed.  
Contractor responsible to verify  
current conditions



**CBJ CORROSION CONTROL PROJECT  
H-PILE PHOTOS**



C7 Cap from Southeast



C7 Cap from South

**FOR INFORMATION ONLY**


Conditions may have changed.  
Contractor responsible to verify  
current conditions



**CBJ CORROSION CONTROL PROJECT  
H-PILE PHOTOS**



C.5 Line Composite from South (D Line in Background)



C.5 Line from Northwest

**FOR INFORMATION ONLY**

Conditions may have changed.  
Contractor responsible to verify  
current conditions



**CBJ CORROSION CONTROL PROJECT  
H-PILE PHOTOS**



C.5 Line from Southwest, Shear Wall – Piles 6 - 10



C.5 Line from Southwest, Piles 8 - 10

**FOR INFORMATION ONLY**

Conditions may have changed.  
Contractor responsible to verify  
current conditions



**CBJ CORROSION CONTROL PROJECT  
H-PILE PHOTOS**



C.5 Pile 10 from Southwest



D Line Composite from South (D.5 in Background)

**FOR INFORMATION ONLY**

Conditions may have changed.  
Contractor responsible to verify  
current conditions



**CBJ CORROSION CONTROL PROJECT  
H-PILE PHOTOS**



D Line at Low Tide, from Southwest (D.5 in Background)



D Line from Northwest, Piles 5 - 7

**FOR INFORMATION ONLY**

Conditions may have changed.  
Contractor responsible to verify  
current conditions



**CBJ CORROSION CONTROL PROJECT  
H-PILE PHOTOS**



D Line, Piles 9 & 10 from Southwest (Note Gabions)



D.5 Line from South

**FOR INFORMATION ONLY**

Conditions may have changed.  
Contractor responsible to verify  
current conditions



**CBJ CORROSION CONTROL PROJECT  
H-PILE PHOTOS**



D.5 Line from Northwest



D.5 Line from Northwest – Close Up



E and D.5 Lines from Northwest

**FOR INFORMATION ONLY**

Conditions may have changed.  
Contractor responsible to verify  
current conditions



**CBJ CORROSION CONTROL PROJECT  
H-PILE PHOTOS**



E Line from Northwest



E.5 and E Lines from Northwest

**FOR INFORMATION ONLY**

Conditions may have changed.  
Contractor responsible to verify  
current conditions



**CBJ CORROSION CONTROL PROJECT  
H-PILE PHOTOS**



E.5 Line from Southwest



E.5 Line from Northwest

**FOR INFORMATION ONLY**

Conditions may have changed.  
Contractor responsible to verify  
current conditions



**CBJ CORROSION CONTROL PROJECT  
H-PILE PHOTOS**



F Line from Northwest



F Line from Southwest

**FOR INFORMATION ONLY**

Conditions may have changed.  
Contractor responsible to verify  
current conditions



**CBJ CORROSION CONTROL PROJECT  
H-PILE PHOTOS**



F Line from Southwest – Close Up



F.5 and F Lines from Southwest

**FOR INFORMATION ONLY**

Conditions may have changed.  
Contractor responsible to verify  
current conditions



**CBJ CORROSION CONTROL PROJECT  
H-PILE PHOTOS**



F.5 Line & J-Box from South (Note Rocks Trapped in Mortar in Left Web)



F.5 Pile from West (Note Rocks Trapped in Web in Concrete Bleed from Casting Beam)

**FOR INFORMATION ONLY**

Conditions may have changed.  
Contractor responsible to verify  
current conditions



**CBJ CORROSION CONTROL PROJECT  
H-PILE PHOTOS**



F.5 Pile from Southwest (Note Rocks Trapped in Web from Concrete Bleed when Casting Beam)



G and F.5 Lines from Northwest

**FOR INFORMATION ONLY**

Conditions may have changed.  
Contractor responsible to verify  
current conditions

**CBJ CORROSION CONTROL PROJECT  
H-PILE PHOTOS**



G Line from Northwest



G Line from North – Close Up

**FOR INFORMATION ONLY**

Conditions may have changed.  
Contractor responsible to verify  
current conditions