April 8, 2009

Airport Board
Juneau International Airport
City and Borough of Juneau
1873 Shell Simmons Drive
Juneau, AK 99801

RE: Common Wall Drainage

The Channel Flying Hangar and the Airport Sand Storage Building share a common wall.

Alaska Airlines sold these two connected hangars in the late 70's. Although there was a requirement to sheetrock the common wall there was no maintenance contract or agreement between the two owners. The airport was the second owner after Alaska Airlines and that purchase took place, I believe, in the mid 80's there was no maintenance agreement or contract between Channel Flying and the Airport at that time. Channel Flying found it necessary to maintain the trough in order to eliminate flooding of their offices and anything stored on the floor on the west side 30' of their hangar. This was accomplished by circulating hot water from a boiler up the south wall, across the 120' trough, down the north wall drain pipe, and back. A used oil boiler, oil tank and compressor installed in a 28ft freezer van outside of the south wall was used to accomplish this. No additional heat is used from the boiler. There is one circulator pump and the sole purpose is to keep snow from building up in the trough or on the roof.

Last fall Cameron Plumbing red tagged the 24 year old boiler and due to unavailable parts and additional expense of maintenance it was determined that replacement was necessary. We met with Airport Manager and discussed options. It was our recollection that ,at that time, he recognized the obligation of the airport to share the expenses of the common wall. Mr. Palmer had the airport engineer come over and see if we could come up with a better plan. No other possibilities were brought up and replacing the boiler was the only option. All American Plumbing was contracted and the boiler was replaced a few weeks after the first snow.

When I submitted the bill to the airport manager he informed me that he checked with the City Attorney and it was his opinion that the Airport had no liability with the shared trough. The advice we received differs from this substantially.

We have two goals. The first one is to address the cost of replacing the boiler and the All American Plumbing bill. The second is to agree on a maintenance agreement between the two hangar owners that address the common wall and drainage issues.

Give it some thought and I will wait to hear from you.

Craig Loken Channel Flying 723-7880



iHlst	01	4.7	1	- Foreign and	ooddii ballin

ALL AMERICAN PLUMBING & HEATING LLC RESIDENTIAL PLUMBING & HEATING SERVICE	DO BOX 331	79	
9229 Emily Way - Juneau, Alaska 99801 789-1800	JUNEOU, AK	99602	
		1100	
70hi 41%		The state of the s	
INSTAUTA NEW USED OF	BOTHER :	W CCLT	
PFreD IN TO ROCK 5	NOW MELT	1	74
DID NOT DIRE TUTO HETTER	I TO HANC		1.01.
Componers, purp, sprover 100			15 8410
Compression, Ful Filter Tradure	s Allpars,		- John Mary
Nearly of on System	11 C & HACK /	100 J	HAUTUP TO THE
· exception			
CHOCANINA MILITARY ATTERNATION OF THE PROPERTY			
			\\$ 
Thereby authorize the work described above and agree to the terms and conditions. Trecognize the hold ALL AMERICAN PLUMBING & HEATING LLC blameless for any damage or destruction to the	nat aged and deteriorated plumbing fixt	ras pining may as la	A Property of the Control of the Con
hold ALL AMERICAN PLUMBING & HEATING LLC blameless for any damage or destruction to the services received. As a matter of policy, refunds and or adjustments are made in the form of certific property or the owner's agent, and have authority to order said work. A service charge of 2% per refunds and or adjustments are made in the form of certification.			
==== 361.40-INV#1562	nunun (24% annuai) wii) be charged on	all balances 30 days or mo	ore past due.
10079 9100 Payment Method		Call Out Fee:	\$26
Check# Cash	:	Additional Charges:	
☐ Credit Card ☐ Visa		Service #1:	16,970.00
CC: _		Service #2:	
00		Service #3:	
EXP:/CCV		Subtotal:	
	Tax:	375.00	
Thank you for the opportunity to serve you!	Total:	910000	
		Paid:	8245.00
Signature:	!	Remainder Due:	

HARRY FLATRY

## COMMON TROUGH DRAINAGE

