

Microwave dish on Hose Tower–Remove & Reinstall. Coord. W/Proj. Mgr.

Security Camera-Remove & Reinstall (Typ.)



Ext. Speakers- Remove & Reinstall (Typ.)



Reinstall "Millenium" wiring & keypad at Existing locations on new siding. 3x loc's.



Microwave dish #2 Remove & Reinstall. Coord. W/Proj. Mgr.




Uni-Strut mounting detail



North- Dispatch office: SIDA fencing to be rolled up, secure w/Temp fencing. Note man-door on Right (arrowed) to be replaced is on SIDA side.




2017– Roof Replacement project. PVC roofing at parapet, typ. Detail before flashing.





Exist. Scupper to be raised—A802, Detail 6

Same scupper.



Exist. Wall Assb'y—NE Corner of 2018 rot repair.





Exist. Scupper to be raised—A802, Detail 6 –Outboard view.