


## **ATTACHMENT #6**



Casework fronts installed to receive tenant furnished ticket counters behind.



Lap top counter installation in process in seating area.



Railing installation in process at stair and ramp.

Note: escalator side panels will have artist design as part of the art program

Drywall finisher prepping escalator sidewall for paint.









Three of the four artwork pieces shown as part of the 1% for Art Program.

Top Left: Artist installing mural near toilet room entrance (Alison Bremmer).

Top Right: Mobile art pieces herring/net hung from ceiling (Rachael Juzeler).

Left: Native carving along balcony wall above Gate 1 (*Robert Mills*).

As noted: Art panels on escalator & mezzanine currently under production; not installed yet (Crystal Worl).

Page 4 of 6



Balcony w/ wood & glass railing installed; admin suites off balcony.

Airport Admin conference room looking out toward balcony.



Airport Admin project office with glass partitioned offices beyond. Allows natural light into inner admin hallway, rooms.



Excavation for ramp paving along west (airfield/ramp) side of building.