

Pump Station Repair Photos
Outer Drive and West Juneau Pump Station Repair
Contract Number: E11-029



Outer Drive - Influent Slide Gate Installation



Outer Drive – Influent Slide Gate, Leaf



Outer Drive – Influent Slide Gate, Left Side



Outer Drive – Influent Slide Gate, Pipe Flange



Outer Drive - Influent Slide Gate, Right Side



Outer Drive – Pump Suction Pipe



Outer Drive – Pump Suction Pipe Wet Well Penetration



Outer Drive – Pump Suction Pipes



Outer Drive – Wet Well Pump Intake



West Juneau – Influent Slide Gate Installation Gate



West Juneau – Influent Slide Gate Leaf



West Juneau – Pump Suction Pipes



West Juneau – Pumps and Suction Pipes



West Juneau – Wet Well Pump Intake