

Juneau International Airport – Routine Facility Inspection Form – 2020 MSGP
(Quarterly & Monthly During Deicing Season)

March

General Information									
Date of Inspection:	3/27/2025		Weather:		Temperature:	49°F			
Time of Inspection:	0900				Wind:	18 KTS @ 1360			
Reason for Inspection:	☒ Routine ☐ Pre Storm Event ☐ Storm Event ☐ Post Storm Event ☐ Complaint				Precipitation:	NONE			
Visual Assessments Reviewed?	☒ Yes ☐ No		Inspector's Name:		Snow Cover:	0"			
Benchmark Monitoring Results Reviewed?	☒ Yes ☐ No		Inspector's Signature:						
Area of Airport Inspected									
Location	Any non-stormwater discharges occurring at time of inspection?		Any previously unidentified discharges of pollutants from the site?		Any control measures needing installation maintenance or repairs?		Any evidence of, or immediate potential for, pollutants entering the storm drainage system?		
Inspection Area									
A. NW Hangars	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	
AA. NW Development Area	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	
B. Alex Holden Way Complex	☐ Yes	☒ No	☐ Yes	☒ No	☒ Yes	☐ No	☐ Yes	☒ No	
C. Fuel Farm	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	
D. Cessna Drive Complex	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	
E. Maintenance Shop / FedEx	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	
F. Main Ramp	☐ Yes	☒ No	☐ Yes	☒ No	☒ Yes	☐ No	☐ Yes	☒ No	
G. Terminal	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	
H. East Ramp Complex	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	
I. East Hangars	☐ Yes	☒ No	☐ Yes	☒ No	☒ Yes	☐ No	☐ Yes	☒ No	
J. Glacier Fire Station	☐ Yes	☒ No	☐ Yes	☒ No	☒ Yes	☐ No	☐ Yes	☒ No	
K. National Guard Ramp	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	
L. National Guard Complex	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	
M. Temsco	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	
MM. NE Development Area	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	
N. Float Pond Outfalls	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	
O. Runway/Taxiways	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	
Outfalls									
1. Lower Duck Creek	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	
2. Upper Duck Creek - 1	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	

3. Upper Duck Creek - 2	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No
4. Jordan Creek Pond	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No
5. Yandukin Culvert	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No
6. Terminal Area Discharge	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No
9. NE Dev Area Outlet	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No
10. TW G Culvert	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No
11. Jordan Creek Culvert Outlet	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No
12. TW D-E Infield Drainage	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No
13. RW Trench Drain Outlets	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No
14. NW Dev. Area Outlet	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No
15. Pond Parking Area Outlet	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No
16. Pond Discharge to River	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No
Inflows										
I. La Perouse - 1	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No
II. La Perouse - 2	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No
III. La Perouse - 3	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No
IV. La Perouse - 3	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No
V. Duck Creek	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No
VI. Jordan Creek	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No
VII. Egan Drive Culvert	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No
VIII Fred Meyer Culvert	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No	☐ Yes	☒ No

Describe any previously unidentified discharges of pollutants on site or any control measures needing maintenance or repairs:	FALLING CATCH BASIN - Alex Holden Complex, EAST HANGARS, GLACIER FIRE STATION.	
Observations of physical condition of and around outfalls, dissipation devices or other storm water management control devices, evidence of pollution in discharges and/or the receiving waters:	N/A	
General Site Conditions		
*The following questions relate to general site conditions at the time of the inspection		
Observations	Yes	No
Are natural resource areas such as streams, wetlands and lakes being effectively protected from storm water discharges with appropriate BMPs?	☒	☐
Are there any slopes or disturbed areas needing proper stabilization or BMP implementation?	☐	☒
Are materials which are potential storm water contaminants stored inside or covered?	☒	☐
Are there any uncontrolled non-storm water discharges?	☐	☒
Are there any other site conditions that warrant additional attention, corrective action, any incidents of non-compliance, or revisions needed to the SWPPP?	☐	☒
In areas where spills and leaks have occurred in the past 3 years, was a re-inspection performed?	☒	☐
Comments or Corrective Action Required		
DUCK CREEK WASTEWATER TREATMENT PLANT PH 23-I-0093 ON 12/24.		

Certification Statement	
I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those person directly responsible for gathering the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.	

Signature: Patricia K. Wabbe Date: 4-3-2025
 Print Name: Patricia K. Wabbe Title: Airport Manager